Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

860 8622 26TH AVE NY Spills S102238616 NNW 8622 26TH AVE N/A

NNW 8622 26TH AVE > 1 BROOKLYN, NY

1.165 mi. 6153 ft.

 Relative:
 SPILLS:

 Higher
 Name:
 8622 26TH AVE

 Actual:
 Address:
 8622 26TH AVE

 10 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9512232 / 2003-09-29

Spill Number/Closed Date: 9512232 / 200 Facility ID: 9512232

Facility Type: ER DER Facility ID: 250911 310856 Site ID: DEC Region: 2 Spill Cause: Unknown Spill Class: C3 2401 SWIS: Spill Date: 1995-12-29 Investigator: **RWAUSTIN** Referred To: Not reported Reported to Dept: 1995-12-29 CID: 257

Water Affected: Not reported Spill Source: Private Dwelling Spill Notifier: Local Agency Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0 Date Entered In Computer: 1995-12-29

Date Entered In Computer: 1995-12-29

Spill Record Last Update: 2003-09-29

Spiller Name: Not reported

Spiller Company: UNKNOWN

Spiller Address: Not reported

Spiller Company: 999

Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

AUSTIN 9/29/03 - AUSTIN - DUE TO LACK OF ANY FURTHER INFO IN THIS MATTER, CLOSED IN DATABASE - ORIG. ASSIGNED TO MULQUEEN - END"

Remarks: "oder og gas in area still checking for "

All Materials:

Site ID: 310856 Operable Unit ID: 1023181 Operable Unit: 01 553721 Material ID: Material Code: 0009 Material Name: gasoline Case No.: Not reported Material FA: Petroleum Quantity: .00 Units: G .00 Recovered:

Oxygenate: Not reported